

















Structure RCC frame

Walls 6" thick concrete blocks for external walls and

4" thick concrete blocks for internal blocks

Flooring 2X2 vertrified tile for living, dining and bedrooms

Windows

Teak wood frame with OST shutter for main doors.

Non-teak frame for flush shutters for other door.

Aluminium/ wooden windows with safety grill

Toilets Anti-skid ceramic tiles for flooring.
Glazed and ceramic tiles dado upto 7" with

high quality C.P fittings and sanitary fittings

Electricals Concealed copper wiring with adequate light,

fan, power points, telephone and T.V points in the living room and master bedrooms

Painting Emulsion for internal walls, snowcem for external walls and enamel paints for wood works

Elevators 4 branded elevators of suitable capacity

Back-up 1KW power back-up for each flat

Water Supply adequate water supply through borewell provision and corporation water in kitchen



TOTAL SITE AREA - 67965.95.58. [or] 6306.95.5gm (or) 1.537988 Acres

Total Assa Jan S Floors 1,00,075,00 S.R. Novel Blats per Floor 29

Annual Control					
COLUMN TWO IS NOT THE OWNER.					
44	.199	-	SECTION.	-	AND PROPERTY.
MI.	199.	-	Chie	900	(96)46
90	188	-	004	***	900
	199	-	100	1000	1996
80		-	000	196	- tope
*	19th	100	989	200	THE PERSON
*	1996	- 0.0		200	968
83	186	-	destr.	200	1994
80	100	200	100	(mm)	100.0
46	Amer	- 54	466	See.	- size-
m.		-	(new)	204	200.00
360	100	-	(major	254	met:
200 000 000					
81	.100	-	1000	200	
41.3	1800	-	169,40	30.00	-00.0
40	1696	194	199.6	10.0	-00-0
80	100	-		100	1946
90	100	-		-	
*	100	-	000	94	
*	1986	100	900	1945	198,8
*		-		Ma.	100.0
(00)	100	100	100	(See	
200 (00) 100					
77.		(me)	1956	-	200
19.	-1646	.00		909	200
10:3		-		26.00	Selection .
10	104	-	inna.	0.00	1944
(8)	188	-	14040	000	4640
99.		198	-010 to	CHT.	2000
10	1690	ter	1916	Port.	Address
1	188	104	000	104	100.00
-	100	Spa	1816	dom:	



